

**CURRENT REVISION LEVELS
FOR
INSTRUCTIONS FOR CONTINUED AIRWORTHINESS (ICA), FLIGHT MANUAL SUPPLEMENTS (FMS) AND SA52**
Revised: 24 February 2025

| AIRCRAFT | STC No. | ICA MANUAL | REVISION LEVEL/DATE | FMS | REVISION LEVEL/DATE | SA52 REVISION LEVEL/DATE |
|--|-----------|----------------------|----------------------------|-------------|----------------------------|--------------------------|
| Gulfstream Aerospace 1125 Westwind Astra, Astra SPX, G150 and G100 | SA01213CH | 6040-1MM | Revision 1 25 Jul 2007 | 6040-1FMS | Revision 3 28 Dec 2007 | Revision 98 Feb 2025 |
| Agusta A109, A109A, A109A II, A109C, A109E, A109K2, A119 | SR02257CH | 7005MM | Revision IR 31 Jan 2006 | 7005FMS | Revision – 02 Mar 2006 | Revision 98 Feb 2025 |
| Agusta A109E, A109K2, A119, AW119 MKII | SR02894CH | 7010MM | Revision 5 07 Oct 2020 | 7010RFMS | Revision 6 14 Feb 2022 | Revision 98 Feb 2025 |
| Agusta AW109SP, A109S | SR02974CH | 7011MM | Revision 9 02 Mar 2017 | 7011FMS | Revision 5 03 Mar 2015 | Revision 98 Feb 2025 |
| Agusta AW109SP, A109S | SR02981CH | ICA – 16A02390001 | Revision 1 27 Jun 2014 | 19A02390001 | Revision 1 30 Jul 2014 | Revision 98 Feb 2025 |
| Agusta AW109SP, A109S | SR02978CH | ICA – 16A02240001 | Revision 1 27 Jun 2014 | 19A02160001 | Revision 1 30 Jul 2014 | Revision 98 Feb 2025 |
| Agusta AW109SP, A109S | SR02977CH | ICA – 16A02160003 | Revision 1 27 Jun 2014 | N/A | -- | Revision 98 Feb 2025 |
| Agusta AW109SP, A109S | SR02982CH | ICA – 16A02160002 | Revision 1 27 Jun 2014 | N/A | -- | Revision 98 Feb 2025 |
| Agusta AW109SP, A109S | SR02980CH | ICA – 16A02160001 | Revision 1 27 Jun 2014 | N/A | -- | Revision 98 Feb 2025 |
| Agusta AW139 | SR03265CH | 7012MM | Revision 2 26 Jul 2017 | 7012FMS | Revision 2 22 Dec 2017 | Revision 98 Feb 2025 |
| Airbus A319-133, A319-115, A320-214, A320-232 | ST02340CH | 6072-5MM | Revision 13 26 Sep 2016 | 6072-5FMS | Revision 8 05 Dec 2016 | Revision 98 Feb 2025 |
| Airbus Helicopters SA330J, AS332C1, AS332L, AS332L1, EC225LP | SR269CH | 2061MM | Revision 3 06 July 2023 | 2061FMS | Revision 3 06 July 2023 | Revision 98 Feb 2025 |
| Bae Systems Avro 146-RJ100A, 146-RJ70A | ST02841CH | 6052MM | Revision – 26 Oct 2009 | 6052FMS | Revision IR 25 May 2010 | Revision 98 Feb 2025 |
| Beechcraft 1900C and 1900D | SA01213CH | 6003MM | Revision 3 14 May 2018 | 6003FMS | Revision 3 20 Dec 2018 | Revision 98 Feb 2025 |
| Beechcraft Hawker 200, A100-1, 200C, 200T, 200CT, A200, A200C, A200CT, B200, B200C, B200T, B200CT | SA00882CH | 6014-DMS MM | Revision – 21 May 2015 | FMS6014-DMS | Revision – 08 May 1998 | Revision 98 Feb 2025 |
| Beechcraft 65-90, 65-A90, B90, C90A, E90, C90GT, C90GTi | SA01213CH | 6011MM | Revision 1 02 Nov 2011 | 6011FMS | Revision 2 29 Nov 2011 | Revision 98 Feb 2025 |

| AIRCRAFT | STC No. | ICA MANUAL | REVISION LEVEL/DATE | FMS | REVISION LEVEL/DATE | SAS2 REVISION LEVEL/DATE |
|--|-----------|------------|---------------------------|-------------|----------------------------|--------------------------|
| Beechcraft 200, A100-1, 200C, 200T, 200CT, A200, A200C, A200CT, B200, B200C, B200T, B200CT, B200GT, B200CGT, 300, 300LW | SA01213CH | 6014MM | Revision 5 13 Feb 2015 | 6014FMS | Revision 8 20 Apr 2015 | Revision 98 Feb 2025 |
| Textron Aviation B300, B300G (KA 350) | SA01213CH | 6008MM | Revision 5 31 Mar 2023 | 6008FMS | Revision 11 12 Sep 2024 | Revision 98 Feb 2025 |
| Bell 205A, 205A-1, 205B, 212, 412, 412EP | SA01213CH | 2055MM | Revision 1 29 May 2009 | 2055FMS | Revision 3 08 Sep 2009 | Revision 98 Feb 2025 |
| Bell 407 | SR01936CH | 7002MM | Revision 4 02 Feb 2022 | 7002FMS | Revision 5 09 Dec 2022 | Revision 98 Feb 2025 |
| Bell 429 | SR04489CH | 7015MM | Revision – 06 Apr 2020 | 7015FMS | Revision - 16 Oct 2020 | Revision 98 Feb 2025 |
| Boeing 737-700, 737-800 | ST02843CH | 6074-1MM | Revision 5 30 Sep 2020 | 6074-1FMS | Revision 5 29 Mar 2022 | Revision 98 Feb 2025 |
| Boeing 747-400, 747-8 | ST03008CH | 6073-2MM | Revision 3 27 May 2016 | 6073-2FMS | Revision 3 30 Jun 2016 | Revision 98 Feb 2025 |
| Boeing 777-300ER Series | ST04017CH | 6076MM | Revision 5 12 Jan 2022 | 6076FMS | Revision 3 25 Oct 2022 | Revision 98 Feb 2025 |
| Cessna 208, 208B | SA02930CH | 6006MM | Revision – 01 Dec 2008 | 6006FMS | Revision IR 30 Nov 2010 | Revision 98 Feb 2025 |
| Cessna 401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C, 425 | SA01213CH | 2007MM | Revision 1 04 May 2005 | 2007FMS | Revision 3 23 May 2005 | Revision 98 Feb 2025 |
| Cessna 441 | SA02935CH | 6078MM | Revision 1 10 Aug 2010 | 6078FMS | Revision – 12 Jul 2010 | Revision 98 Feb 2025 |
| Cessna 500, 550, 560 | SA01213CH | 2009MM | Revision 3 10 Jun 2014 | 2009FMS | Revision 4 04 Aug 2014 | Revision 98 Feb 2025 |
| Cessna 510 | SA02897CH | 6053MM | Revision 3 12 Jun 2013 | 6053FMS | Revision 2 26 Aug 2013 | Revision 98 Feb 2025 |
| Cessna 525, 525A, 525B, 525C | SA03241CH | 6049MM | Revision 3 01 Aug 2016 | 6049FMS | Revision 3 02 Feb 2017 | Revision 98 Feb 2025 |
| Cessna 560XL | ST01138CH | 6050-XLMM | Revision 5 01 Mar 2021 | 6050-XL-FMS | Revision 6 18 Mar 2021 | Revision 98 Feb 2025 |
| Bombardier Inc. Challenger CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-604, CL-601-3A and CL-601-3R), CL600-2B19 (CRJ200) | ST01612CH | 6041MM | Revision 6 22 Aug 2018 | 6041FMS | Revision 10 06 Dec 2018 | Revision 98 Feb 2025 |
| Dassault-Aviation Falcon 10 | ST02395CH | 6032-10MM | Revision – 02 Jan 2007 | 6032-10FMS | Revision – 19 Mar 2007 | Revision 98 Feb 2025 |
| Gulfstream GV, GV-SP and GIV-X | ST01159CH | 6037-VMM | Revision 2 09 Sep 2020 | 6037-VFMS | Revision 5 11 Mar 2021 | Revision 98 Feb 2025 |

| AIRCRAFT | STC No. | ICA MANUAL | REVISION LEVEL/DATE | FMS | REVISION LEVEL/DATE | SAS2 REVISION LEVEL/DATE |
|--|-----------|------------|-----------------------------------|-----------|--------------------------------|--------------------------|
| Hawker Beechcraft 400, 400A | ST03255CH | 6047MM | Revision 1 06 Aug 2013 | 6047FMS | Revision – 28 Aug 2013 | Revision 98 Feb 2025 |
| Hawker Beechcraft BAe.125 Series 1000A; BAe.125 Series 1000B; BAe.125 Series 800A; BAe.125 Series 800B; BH.125 Series 400A; BH.125 Series 600A; DH.125 Series 400A; Hawker I 000; Hawker 800; Hawker 800XP; Hawker 850XP; Hawker 900XP; HS.125 Series 400B; HS.125 Series 400B/1; HS.125 Series 401B; HS.125 Series 403A(C); HS.125 Series 4038; HS.125 Series 600A; HS.125 Series 600B; HS.125 Series 600B/1; HS.125 Series 600B/2; HS.125 Series 600B/3; HS.125 Series 700A; HS.125 Series 700B; HS.125 Series F400B; HS.125 Series F403B; HS.125 Series F600B | ST02068CH | 6033-2MM | Revision 3 21 Feb 2017 | 6033-2FMS | Revision 4 09 Nov 2011 | Revision 98 Feb 2025 |
| Israel Aircraft Industries Westwind 1124 and 1124A | ST02429CH | 6043MM | Revision 1 12 Jul 2021 | 6043FMS | Revision 2 24 Feb 2022 | Revision 98 Feb 2025 |
| Jetstream 3201 | SA02177CH | 6034-1MM | Revision 1 10 Aug 2010 | 6034-1FMS | Revision 4 29 Aug 2011 | Revision 98 Feb 2025 |
| Learjet 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 31, 31A, 35, 35A, 36, 36A | SA01213CH | 6017MM | Revision 2 31 Jan 2011 | 6017FMS | Revision 6 15 Mar 2011 | Revision 98 Feb 2025 |
| Learjet 45 | ST01651CH | 6015MM | Revision 4 02 June 14 | 6015FMS | Revision 5 08 Jul 2014 | Revision 98 Feb 2025 |
| | | 6015-1MM | Revision 6 18 Oct 2023 | 6015-1FMS | Rev 5 27 Sep 2023 | |
| Learjet 55, 55B, 55C and 60 | SA01213CH | 6018MM | Revision 4 22 Sep 2014 | 6018FMS | Revision 10 14 Feb 2019 | Revision 98 Feb 2025 |
| Piaggio P-180 | SA03345CH | 6054MM | Revision – (IR) 07 Feb 2013 | 6054FMS | Revision – 08 Jan 2014 | Revision 98 Feb 2025 |
| Pilatus PC-6/B2-H4 | SA04403CH | 6056MM | Revision 1 14 Mar 2019 | 6056FMS | Revision – (IR) 14 Jun 2019 | Revision 98 Feb 2025 |
| Pilatus PC-12, 12/45, 12/47, 12/47E | SA02488CH | 6045MM | Revision 5 17 July 2023 | 6045FMS | Revision 8 18 Sep 2024 | Revision 98 Feb 2025 |
| Piper PA-31, PA-31-300, PA-31-325, PA-31-350 | SA1666GL | 2002MM | Revision 2 20 Apr 2007 | 2002FMS | Revision 2 21 May 2007 | Revision 98 Feb 2025 |

| AIRCRAFT | STC No. | ICA MANUAL | REVISION LEVEL/DATE | FMS | REVISION LEVEL/DATE | SAS2 REVISION LEVEL/DATE |
|--|-----------|------------|---------------------------|-----------|----------------------------|--------------------------|
| Piper PA-31T, PA-31T1, PA31T2, PA31T3, PA-31P, PA-31P-350 | SA00560CH | 2003MM | Revision 1 02 Apr 2008 | 2003FMS | Revision 1 12 May 2008 | Revision 98 Feb 2025 |
| Piper PA-42, PA-42-720, PA-42-1000 | SA00972CH | 6004MM | Revision – 10 Jul 2012 | 6004FMS | Revision 2 22 Aug 2012 | Revision 98 Feb 2025 |
| Beechcraft 100, A100, A100A, B100 | SA01213CH | 6012MM | Revision – 23 Sep 2008 | FMS6012 | Revision – 18 Apr 2000 | Revision 98 Feb 2025 |
| Sikorsky S-76A and S-76C | SR04023CH | 7003MM | Revision 3 23 Oct 2024 | 7003FMS | Revision 2 14 Aug 2024 | Revision 98 Feb 2025 |
| Sikorsky S-92A | SR02666CH | 7009-1MM | Revision 3 28 Mar 2016 | 7009-1FMS | Revision 4 19 May 2016 | Revision 98 Feb 2025 |
| Viking Air Limited DHC-6-400 (Twin Otter) | SA04486CH | 6080MM | Revision 1 03 Jan 2020 | 6080FMS | Revision 1 06 Oct 2020 | Revision 98 Feb 2025 |
| Boeing 787-8, 787-9 | ST04609CH | 6081MM | Revision – 01 May 2019 | 6081FMS | Revision 1 16 Nov 2022 | Revision 98 Feb 2025 |
| Daher Aircraft Kodiak 100 | SA04554CH | 6055MM | Revision - 07 Dec 2017 | 6055FMS | Revision IR 23 Dec 2021 | Revision 98 Feb 2025 |
| Pilatus Aircraft Limited PC-24 | SA11832CH | 6046MM | Revision 1 21 Nov 2024 | 6046FMS | Revision 1 28 Jan 2025 | Revision 98 Feb 2025 |
| AIRBUS HELICOPTERS DEUTSCHLAND GmbH (AHD), MBB-BK 117 D-3 | SR04658CH | 7016MM | Revision - 15 May 2022 | 6046FMS | Revision - 19 July 2024 | Revision 98 Feb 2025 |

For Electronic updates please contact: amy@spectrum-aeromed.com